# DH_XVR4x08-I3_MultiLang V4.001.0000005.1.R.240806

## Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

# Legal Information

## Copyright

## Trademarks

## Disclaimer

# Table of Contents

# 1 Release Notes

## 1.1 Overview

| | |
|---|---|
| Product name | Digital Video Recorder (DVR) |
| Version | V4.001.0000005.1.R.240806 |
| Software package information | DH_XVR4x08-I3_MultiLang_V4.001.0000005.1.R.240806.zip |
| OS requirement | None |
| Release date | August 19, 2024 |

## 1.2 New Features

| Function | Description |
|---|---|
| None | This version fixes some bugs improves the product performance and strengthens product security on the basis of the last version. It does not update the functions. For instructions on product functions refer to previously published materials. |

## 1.3 Fixed Bugs

Fix some bugs.

## 1.4 Compatibility

## 1.4.1 Program

This new baseline version is V4.001.0000005.1.R and the security baseline version is 2.3. If the earlier baseline programs (V4.001.0000005.0.R and earlier) are updated to this version, we recommend not revert them to the earlier version.If reverting the earlier version, it is recommended that you restore the device to default.

## 1.4.2 Third-party Access

ONVIF 22.12(Profile T; Profile S; Profile G); CGI; SDK

## 1.5 Software Environment

| Category | Model | Version |
|---|---|---|
| Software | Player | V4.001.0000004.0 |

| Category | Model | Version |
|---|---|---|
|  | COS PRO | V1.300.0000000 |
|  | DSS PRO | V8.3.0 |
|  | NetSDK | General_NetSDK_Eng_Win32_IS_V3.055.0000001.0.R.211101 |
|  | DiskManager | General_DiskManager-Win32_Eng_V1.000.0000003.2.R.200422 |
|  | ConfigTool | General_ConfigTool_ChnEng_V5.001.0000002.0.R.20230223 |
| DMSS | / | Android：1.99.600 |
|  | / | IOS：1.99.600 |

## 1.6  Pending Issues

None.

## 1.7  Update Guide

Refer to the following instructions when updating the product.

1. You can update the device through ConfigTool, webpage and USB flash drive. For details, see the update guide.
2. During the update, the device will stop some services, such as recording and live view. After the update is complete, restart the device to resume normal operation.
3. The update does not affect the previous configuration.
4. Do not disconnect the power supply during the update. Otherwise the device might not be able to start normally.

ENABLING A SAFER SOCIETY AND SMARTER LIVING